

Sikorsky S-76B

INSPECTIONS

S/N: 760356. AFTT: 7197.9* Annual Inspections: 14th November, 2014.

The following inspections were completed by:
UK Aviation Services (Engineering) Ltd at Blackpool Airport.

(*AFTT Current at 27/12/2014.)

Description / Work Summary

Airframe Inspections:

ASB-76-65-68 Pt1 TR Blade Pitch Horn Inspection
ASB-76-65-68 Pt2 TR Blade Pitch Horn Inspection
ASB-76-67-54 Fwd / Aft Main Rotor Servo Input Control
ASB-76-73-7 Combustion Drain Line
FAA AD 2001-01-04 Threaded Joint Inspection
100 Hour Inspection
12 Month Inspection
1500 Hour / 12 Month Inspection
300 Hour / 12 Month Inspection
300 Hour / 3 Month Inspection
300 Hour / 6 Month Inspection
50 Hour Inspection
6 Month Inspection
600 Hour / 12 Month Inspection
600 Hour / 6 Month Inspection
900 Hour / 12 Month Inspection

Engine Inspections:

TCAD CF 2003-16 Critical Parts Life Limit Factoring
1200 Hour / 24 Month Inspection (No 2 only)
150 Hour / 12 Month Inspection
150 Hour / 6 Month Inspection
300 Hour Inspection (No 2 Only)
300 Hour / 1 Year Inspection
50 Hour Inspection
750 Hour / 1 Year Inspection
900 Hour / 1 Year Inspection

Avionic Inspections:

50 Hour Inspection
Annual Inspection

Component Inspections:

ASB-76-66-52 Tail Rotor Drive Shaft Flange to Shaft Inspections

Equipment inspections:

First Aid Kit Inspection
Cabin Fire Extinguisher Inspection



(Document updated 05/01/15.)

 **PLANE SAYLING**
AVIATION LIMITED

Contact Stephen Ayling T: +44 (0) 1276 855 340

PlaneSayling Aviation Limited. Building B1H, West Entrance, Fair Oaks Airport, Chobham. GU24 8HX UK.
www.PlaneSaylingAviation.com – sales@PlaneSaylingAviation.com

The offer for sale of this aircraft is subject to contract and the aircraft may at any time be withdrawn from the market without prior notice. Specification is subject to verification by the purchaser.

